



BATTERY HANDLING SYSTEMS

Tech Tip # TSB06-002

Issue Date: August 2006

Collector Trolley Alignment

Models Affected: All Battery Extractors

Subject:

Proper installation and maintenance of collector trolley and tow arm.


Description:

Proper alignment of the collector trolley with the buss duct is very important to prevent premature wearing of the brushes and costly replacement of the collector trolley.

Recommendation:

The collector trolley needs to be properly aligned with the buss duct at the time of installation. The collector trolley should be checked on a regular basis to ensure all hardware is properly attached and that the tow arm has not been bent.

IMPROPER ALIGNMENT



PROPER ALIGNMENT



Repair:

If the tow arm has been bent replacement parts are needed to correct the damage.

For more information call

877-BHS-4YOU.

for the servicing dealer near you.